


1. For Positive Output: do not mount C24, R21, U6
2. For Negative Output: Mount D4, D5 in opposite polarity

Do not mount R20

3. Mount alternatively R13 or R19 depending on FB point
4. Voltage Reference U7 is needed only for Precision Outdoor Applications

HvConverterR2

CRD V.Danielyan 14 Aug 05
Corrected 25 May 06



5. U3-13 and U3-14 Should be soldered together, if not connected on PCB